Dell Storage Center 7.1 Release Notes

This document describes the new features, enhancements, fixed issues, and open issues in Storage Center 7.1.

Current Version: 7.1.2 Release Date: 2016 - 09 Previous Version: 7.1.1

Document Revision History

Document Number: 680-021-019

Revision	Date	Description	
A	August 2016	Initial release of Storage Center 7.1	
В	September 2016	Updated for Storage Center 7.1.2	
С	September 2016	Updated feature support for SC7020	

Contents

Supported Storage Systems	1
Dell Storage Manager 2016 R2	2
New in This Release	2
Storage Center 7.1 Feature Availability and Licenses	6
Storage Center 7.1 Scalability	10
Fixed Issues	12
Open Issues	18
Storage Center Update Information	22
Support Resources	22

Supported Storage Systems

Storage Center 7.1 is supported on the following storage systems:

- SC9000
- SC8000
- SC7020
- SC4020
- SCv2000 series



Dell Storage Manager 2016 R2

Dell Storage Manager 2016 R2 is required to manage storage systems running Storage Center 7.1.

Storage Center 7.1 no longer supports the browser-based GUI known as Storage Center System Manager You must install Dell Storage Manager 2016 R2 before updating a storage system to Storage Center 7.1. If you update a storage system to Storage Center 7.1 without using Dell Storage Manager 2016 R2, you will lose management connectivity to the storage system.



NOTE: The storage system must be running Storage Center 6.6.4 or later to update to Storage Center 7.1.

New in This Release

The following features were added to Storage Center 7.1.

SC7020 Storage System

Storage Center 7.1 introduces support for the SC7020 storage system.

The SC7020 consists of a 3U chassis with dual storage controllers, redundant power supplies, and up to 30 2.5-inch hot swappable SAS hard drives. The SC7020 can be expanded up to 500 drives and it supports SC400 and SC420 12 Gb expansion enclosures and SC280 6 Gb expansion enclosures.



NOTE: Support for upgrading a storage system with SC200 and SC220 expansion enclosures to an SC7020 storage system is planned for a later release.

SC4020 Storage Systems with Front-End SAS Connectivity

Storage Center 7.1 adds support for SC4020 storage system models with front-end SAS I/O cards.



NOTE: An SC4020 storage system with front-end SAS connectivity does not support the Live Volume feature in Storage Center 7.1.

32 Gb FC I/O Card Support

Storage Center 7.1 adds support for a 32 Gb Fibe Channel I/O card.

Support for the 32 Gb Fibre Channel I/O card is currently limited to SC9000 storage systems with a specific configuration of switches and operating systems. See the *Dell Storage Compatibility Matrix* for more information.

4Kn Drive Support

Storage Center 7.1 adds support for native 4K sector drives.

Native 4K drives use a 4096-byte sector size instead of the legacy 512-byte sector size.

Cross-Platform Replication

The cross-platform replication feature provides a method for performing volume replication between PS Series storage arrays and Storage Centers. This feature preserves the functional and operational models in the current replication implementation for each storage system.



NOTE: SCv2000 series storage systems do not support cross-platform replication.

Data Center Bridging (DCB) Support

Storage Center 7.1 supports data center bridging (DCB) services.

Dell Storage Manager displays DCB information for supported I/O cards, such as switch names and features of the switch port that an iSCSI port is plugged into. Dell Storage Manager also displays information about the Link Layer Discovery Protocol (LLDP), which is used to help support DCB.

Data Reduction

Data Reduction uses compression and deduplication to decrease the amount of disk space used by volume data. Compression reduces the amount of space used by a volume by encoding data. Deduplication finds duplicate data in pages then removes the duplicate data, conserving the disk space that would be used by additional copies. When deduplication is used, compression is also applied to a volume.

Drive Age Reporting

Storage Center 7.1 adds support for the Drive Age Reporting feature.

The age of each drive is displayed as **Power On Time** in Dell Storage Manager 2016 R2.

Federation Live Migrate

Storage Center 7.1 adds support for the Federation Live Migrate feature.

Federation Live Migrate allows for the online migration of a volume from one Storage Center to another Storage Center without downtime or disruption to the host server.



NOTE: Federation Live Migrate is supported on SC9000, SC8000, SC7020, and SC4020 storage systems, but it is not supported on SCv2000 series storage systems.

IPv6 Support for Fault Domains and Pinging

Storage Center 7.1 supports IPv6 addresses in iSCSI fault domains as well as other IPv6 features.

- iSCSI fault domains can be created and modified to use ports with IPv6 addresses.
- Dell Storage Manager 2016 R2 can display multiple IPv6 addresses for each physical port, as well as multiple discovered gateway IPv6 addresses.
- Ports can be pinged using an IPv4 or IPv6 address.



NOTE: Replications between Storage Center and PS Series groups do not support IPv6.

Live Volume with Auto Failover in Microsoft Server Environments

Storage Center 7.1 adds support for the Live Volume with Auto Failover feature in Microsoft server environments.

Live Volume with Auto Failover is supported in Microsoft server environments including Windows Server 2012 and Windows Server 2012 R2. In addition, Live Volume with Auto Failover is supported on both Microsoft Hyper-V and Windows clustering environments including Windows clustering on VMware hosts using physical mode raw device mappings (pRDMs).



NOTE: Live Volume with Auto Failover in Microsoft server environments is supported on SC9000, SC8000, SC7020 and SC4020 storage systems, but it is not supported on SCv2000 series storage systems.

Online Import of Volumes from PS Series Storage Arrays

An online import creates a destination volume, maps it to the server, then migrates the data to the destination volume.

In Storage Center 7.1, performing an online import of volumes from PS Series storage arrays is supported on Red Hat Enterprise Linux 7.x, VMware ESXi 5.5 or later, and Windows Server 2008 R2 or later.

Renaming Replays to Snapshots

Starting in this release, Replays are now called snapshots in the Dell Storage Manager Client.

SED Rekey

Storage Center 7.1 supports enhancements for managing self-encrypting drives (SED).



NOTE: The Self-Encrypting Drives feature must be licensed to use Secure Data.

The following features have been added in Dell Storage Manager 2016 R2:

- You can specify a rekey interval for a Secure Disk folder. When that interval has been reached, a rekey is triggered on each disk in the folder.
 - A **Rekey** checkbox has been added to the **Edit Disk Folder Settings** dialog box.
- You can perform an on-demand rekey of a Secure Disk folder.
 - A new option called **Rekey Disk Folder** has been added to the **Disks** menu when a Secure Data folder is selected.
- The process called Rescue Data allows you to copy volumes from a Secure Data folder to another
 folder. The target folder can be either a secure folder or a nonsecure folder. Use the Copy Volumes to
 Disk Folder operation to perform rescue data.

SNMPv3 Support

Storage Center 7.1 supports the use of SNMPv3 and the configuration of SNMPv3 users and trap destinations using Dell Storage Manager 2016 R2.

Storage Redundancy Levels

The storage redundancy recommendations and requirements for HDDs and SSDs have changed in Storage Center 7.1.



NOTE: For SC7020 storage systems, the dual redundancy level is the default for all drives.

Table 1. HDD Redundancy Recommendations and Requirements

Disk Size	Redundancy Level
Up to 966 GB	No recommended or required redundancy level when adding disks of this size to a new or existing page pool
967 GB to 1.9 TB	Dual redundancy is recommended when adding disks of this size to a new or existing page pool
2.0 TB or larger	Dual redundancy is required when adding disks of this size to a new page pool
2.79 TB or larger	Dual redundancy is required when adding disks of this size to an existing page pool

Table 2. SSD Redundancy Recommendations and Requirements

Disk Size	Redundancy Level
Up to 1.7 TB	No recommended or required redundancy level when adding disks of this size to a new or existing page pool
1.8 TB to 3.9 TB	Dual redundancy is recommended when adding disks of this size to a new or existing page pool
4.0 TB or larger	Dual redundancy is required when adding disks of this size to a new or existing page pool

T10-PI Support

Storage Center 7.1 adds support for T10 Protection Information (PI) capable drives.

T10 Protection Information is an end-to-end data integrity feature that protects against silent data corruption.

Volume QoS Profiles

Storage Center 7.1 supports Volume QoS Profiles.

When the Volume QoS Profiles feature is enabled, users can create and manage profiles for Quality of Service (QoS) settings using Dell Storage Manager 2016 R2.

The volume QoS feature allows users to define an arbitrary quality of service for volumes by setting hard limits on volume IOPS or throughput. Using the QoS Profiles feature, a user can apply QoS profiles to a single volume or group of volumes.

By default, Dell Storage Manager provides a single default profile which is used for all volumes. Users can create their own custom profiles and apply them to volumes.

VMware Virtual Volumes Support

Storage Center 7.1 supports VMware Virtual Volumes (VVols) technology.

VMware VVols is a storage management and integration framework designed to deliver a more efficient operational model for attached storage.

A key component of the VVols framework is the VASA 2.0 Provider included as part of Dell Storage Manager 2016 R2. VASA (vSphere Storage APIs for Storage Awareness) is a software management interface between the vCenter server and storage systems. To enable VVols operations between VMware vCenter Server and a Storage Center, the VASA Provider is registered with VMware vCenter server.

Storage Manager includes these user interface enhancements to support VVols:

- Addition of the Register VASA Provider option to the Register Server action.
- New wizards for defining and managing storage containers. A storage container is a pool of storage that is used in a VMware environment in support of virtual volumes. A storage container corresponds to a VVol datastore in the vCenter interface.
- A new datastore type, **VVOL**, can be specified when creating datastores on a VMware vSphere host.
- Updated storage views to include VVol information.

See the *Dell Storage Manager Administrator's Guide* and *Dell Storage Manager Release Notes* for information about VVols requirements and recommendations.

Storage Center 7.1 Feature Availability and Licenses

The core licenses and support for optional licensed features varies depending on the storage system.

SC9000 Features and Licenses

SC9000 storage systems provide the following licensed features and optional value-added bundles.

Core Software Bundle

- Data Instant Replay (Snapshots)
- Data Reduction (Compression and Deduplication)
- Dell Storage Manager
- Dynamic Capacity
- Dynamic Controllers
- · Live Migrate
- Local Data Protection
- Multi-VLAN Tagging
- Virtual Ports
- Volume QoS

VVols

Optional Licenses

- Application Protection Manager Suite
- Live Volume and Live Volume with Auto Failover
- Remote Instant Replay (Replication), including Cross-Platform Replication
- SED FIPS Secure Data
- Storage Manager Chargeback

Storage Protection Bundle

- Application Protection Manager Suite
- Live Volume and Live Volume with Auto Failover
- Remote Instant Replay (Replication), including Cross-Platform Replication

Storage Optimization Bundle

- Data Progression
- Fast Track

Total Feature Bundle

- SED FIPS Secure Data
- Storage Manager Chargeback
- Storage Optimization Bundle
- Storage Protection Bundle

SC8000 Features and Licenses

SC8000 storage systems provide the following licensed features:

Core Licenses

- Data Instant Replay (Snapshots)
- Data Reduction (Compression and Deduplication)
- Dell Storage Manager
- Dynamic Capacity
- Dynamic Controllers
- Live Migrate
- Local Data Protection
- Multi-VLAN Tagging
- Volume QoS
- VVols

Optional Licenses

- Application Protection Manager Suite
- Data Progression
- Fast Track
- Live Volume and Live Volume with Auto Failover

- Remote Instant Replay (Replication), including Cross-Platform Replication
- SED FIPS Secure Data
- Storage Manager Chargeback
- Virtual Ports

SC7020 Features and Licenses

SC7020 storage systems provide the following licensed features and optional value-added bundles.

Core Software Bundle

- Data Instant Replay (Snapshots)
- Data Reduction (Compression and Deduplication)
- Dell Storage Manager
- Dynamic Capacity
- Dynamic Controllers
- Live Migrate
- Local Data Protection
- Multi-VLAN Tagging
- Virtual Ports
- Volume QoS
- VVols

Optional Licenses

- Application Protection Manager Suite
- Live Volume and Live Volume with Auto Failover
- Remote Instant Replay (Replication), including Cross-Platform Replication
- SED FIPS Secure Data
- Storage Manager Chargeback

Storage Protection Bundle

- Application Protection Manager Suite
- Live Volume and Live Volume with Auto Failover
- Remote Instant Replay (Replication), including Cross-Platform Replication

Storage Optimization Bundle

- Data Progression
- Fast Track

Total Feature Bundle

- SED FIPS Secure Data
- Storage Manager Chargeback
- Storage Optimization Bundle
- Storage Protection Bundle

SC4020 Features and Licenses

SC4020 storage systems provide the following licensed features:

Core Licenses

- Data Instant Replay (Snapshots)
- Data Reduction (Compression and Deduplication)
- Dell Storage Manager
- Dynamic Capacity
- Dynamic Controllers
- Live Migrate
- Local Data Protection
- Multi-VLAN Tagging
- Volume QoS
- VVols

Optional Licenses

- Application Protection Manager Suite
- Data Progression
- Fast Track
- Live Volume and Live Volume with Auto Failover
- Remote Instant Replay (Replication), including Cross-Platform Replication
- SED FIPS Secure Data
- Storage Manager Chargeback
- Virtual Ports

Performance/Optimization Bundle

- Data Progression
- Fast Track

Remote Data Protection Bundle

• Remote Instant Replay (Replication)

Remote Data Protection with Live Volume Bundle

- Remote Instant Replay (Replication)
- Live Volume and Live Volume with Auto Failover

SCv2000 Series Features and Licenses

SCv2000 series storage systems provide the following licensed features:

Core Licenses

- Dell Storage Manager
- Dynamic Capacity

• Dynamic Controllers

Optional Licenses

- Flex Port
- Local Data Protection (Snapshots)
- Remote Data Protection (Asynchronous replication only)

Storage Center 7.1 Scalability

The following scalability guidelines apply to Storage Center 7.1.

Storage System Scalability Guidelines

The following scalability guidelines apply to SC9000, SC8000, SC7020, SC4020, and SCv2000 series storage systems.



NOTE: Raw storage space is expressed in decimal units (for example, $1 \text{ TB} = 10^{12} \text{ bytes}$). Addressable storage space is expressed in base 2 units (for example, $1 \text{ TB} = 2^{40} \text{ bytes}$). Therefore, a 1 TB drive measured in decimal units is equal to 0.909 TB base 2 units.

Storage System	Supported Maximum
SC9000 (Dual-Controller) with 128 GB of memory per controller	• 3.1 PB raw and 2.0 PB addressable storage space using the standard 2 MB page size
	 750 TB raw and 500 TB addressable storage space using a 512 KB page size
SC8000 (Dual-Controller) with 64 GB of memory per controller	• 3.1 PB raw and 2.0 PB addressable storage space using the standard 2 MB page size
	 750 TB raw and 500 TB addressable storage space using a 512 KB page size
SC8000 (Dual-Controller) with 16 GB of memory per controller	• 750 TB raw and 500 TB addressable storage space using the standard 2 MB page size
	 400 TB raw and 300 TB addressable storage space using a 512 KB page size
SC7020 (Dual-Controller) with 128 GB of memory per controller	• 3.1 PB raw and 2.0 PB addressable storage space using the standard 2 MB page size
	 750 TB raw and 500 TB addressable storage space using a 512 KB page size
SC4020 with 16 GB of memory per controller	1054 TB raw and 700 TB addressable storage space using the standard 2 MB page size
	 500 TB raw and 400 TB addressable storage space using a 512 KB page size
SCv2000 series with 8 GB of memory per controller	• 672 TB raw and 450 TB addressable storage space using the standard 2 MB page size

Storage Center Scalability Guidelines

The following scalability guidelines are the maximum recommended design guidelines for storage systems running Storage Center 7.1.

SC9000, SC8000, SC7020, and SC4020 Storage Systems

The following scalability guidelines are the maximum recommended design guidelines for SC9000, SC8000, SC7020, and SC4020 storage systems running Storage Center 7.1.

Storage Center Object	Supported Maximum
Disk Folder	50 disk folders
Server	 500 servers (Total number of servers includes physical servers, virtual servers, and server clusters.)
	• 500 server folders
	 1000 server HBA initiator ports (Total number of HBA initiator ports includes all physical and virtual ports that are visible to the SAN.)
Volume	 500 TB maximum volume size (or the maximum addressable storage space, whichever is less)
	• 2000 volumes
	500 volume folders
Deduplication	1 PB data ingestion limit (SC4020 – 500 TB data ingestion limit)
Live Volume	100 Live Volumes
Thin Import	10 volumes (maximum simultaneous imports)
QoS Profiles	• 100 Volume QoS Profiles
	100 Group QoS Profiles
	100 Volumes per Group QoS Profile
Data Instant Replay	• Snapshots:
(Snapshots)	 SC9000 – 32,000 snapshots
	- SC8000 – 16,000 snapshots
	- SC7020 – 16,000 snapshots
	 SC4020 – 4000 snapshots
	• 1000 snapshot profiles
	100 snapshot history profiles
	200 consistency groups
	 100 volumes per consistency group (SC4020 – 40 volumes per consistency group)
Replications	Source replications:
	- SC9000 – 1000 source replications
	 SC8000 – 500 source replications
	- SC7020 – 1000 source replications
	 SC4020 – 250 source replications

Storage Center Object Supported Maximum

2000 target replications (SC4020 – 1000 replications for FC and 230 replications for iSCSI)

SCv2000 Series Storage System

The following scalability guidelines are the maximum recommended design guidelines for SCv2000 series storage systems running Storage Center 7.1.

Storage Center Object	Supported Maximum
Disk Folder	50 disk folders
Server	• 100 servers (Total number of servers includes physical servers, virtual servers, and server clusters.)
	100 server folders
	 200 server HBA initiator ports (Total number of HBA initiator ports includes all physical and virtual ports that are visible to the SAN.)
Volume	500 TB maximum volume size (or the maximum addressable storage space, whichever is less)
	• 1000 volumes
	500 volume folders
Thin Import	10 volumes (maximum simultaneous imports)
QoS Profiles	• 100 Volume QoS Profiles
	• 100 Group QoS Profiles
	100 Volumes per Group QoS Profile
Data Instant Replay	2000 snapshots
(Snapshots)	1000 snapshot profiles
NOTE : Data Instant	100 snapshot history profiles
Replay is a licensed	100 consistency groups
feature.	25 volumes per consistency group
Replications	124 source replications
	500 target replications

Fixed Issues

The following sections summarize the issues fixed in Storage Center 7.1.

Fixed Issues Related to Data Reduction

The following issues are fixed in Storage Center 7.1.

Table 3. Fixed Data Reduction Issue in Storage Center 7.1.2

Issue	Description
SCOS-19580	The front-end I/O performance of a storage system might degrade during data progression after a few terabytes of data are ingested into the Deduplication process.

Table 4. Fixed Data Reduction Issue in Storage Center 7.1.1

Issue	Description
SCOS-14931	On Demand Data Progression may not complete successfully when
	Deduplication is enabled on a volume.

Fixed Issues Related to Hardware

The following issues are fixed in Storage Center 7.1.

Table 5. Fixed Hardware Issues

Issue	Description
SCOS-16637	A 10 Gb iSCSI I/O card is unable to receive data from an Oracle Linux server if the write command is 8,126,464 bytes or larger.
SCOS-15864	A dual controller reset might occur if a single volume is mapped to more than 10 local ports per controller.
SCOS-15697	A dual controller reset might occur due to a data overflow issue with a 10 Gb iSCSI I/O card.
SCOS-15264	A dual controller reset might occur following the deletion of iSCSI remote port configurations.
SCOS-15263	The embedded iSCSI ports might reset because of connection timeouts to remote storage systems.
SCOS-15002	A controller reset might occur because of high memory usage caused by login requests that take a long to time process during heavy I/O.
SCOS-14901	An SCv2000 series controller reset might occur due to an issue with the system profile size.
SCOS-14257	A controller reset might occur because of an issue with deduplication.
SCOS-13499	An SC400 expansion enclosure might report incorrect high temperature warnings.
SCOS-13353	SC8000 controllers with CHA3 cache cards might reset due to a reference to a no longer supported Storage Center subsystem.
SCOS-12881	An SC400 or SC420 expansion enclosure might incorrectly report high temperature warnings.

Issue	Description
SCOS-10740	An SCv2000 series storage system might unexpectedly shut down because of a high operating temperature issue.
SCOS-10012	VMotioning VMs to an SC7020 might cause the datastore to go offline.
SCOS-10010	Auto discovery of an SC7020 might fail in some installation environments.
SCOS-9033	An SCv2000 series or SC4020 storage system running Storage Center 6.5.2 might incorrectly create swap alerts.
SCOS-7943	A controller might reset if the iSCSI initiator logs out from the target, but the initiator fails to terminate the connection.
SCOS-6420	An SCv2000 series controller reset might occur due to an incorrect front-end SAS I/O card critical temperature alert.
SCOS-6338	Storage Center UPS monitoring does not support newer UPS network cards.
SCOS-3400	The embedded iSCSI ports on an SCv2080 series storage system might reset on configurations where there is congestion at the initiator, causing flow control back to the storage system.
SCOS-2570	On rare occasions, a RAID device might not be degraded properly when a second write failure is reported for the same device.
SCOS-2548	An SC9000 controller might reset due to an issue during controller failover.
SCOS-2534	After updating to Storage Center 6.6.5, a controller with iSCSI I/O cards might reset during a front-end rebalance, resulting in an outage.
SCOS-2390	An iSCSI I/O card might send out an Address Resolution Protocol (ARP) request for IP on another network if it cannot find a gateway.
SCOS-2386	A controller might reset if an iSCSI host sends a non-512 byte aligned first burst size when Immediate Data is enabled.
SCOS-2098	Performing a non-service affecting upgrade from a CHA3 cache card to a 4GB Write cache card might cause the upgrade to fail due to card installation errors.
SCOS-1476	A controller might reset and fail-over might be unsuccessful due to an iSCSI I/O cache card memory leak with iSCSI attached Oracle and Linux servers.
SCOS-1408	If TCP RX fragmentation is enabled on iSCSI I/O cards, the card might enter and exit hibernation mode, causing replications to fail.
SCOS-1380	On rare occasions, a single-disk predictive failure might cause high latency because of long disk recovery during I/O.
SCOS-684	A short duration AC line brownout on an SCv2000 series or SC4020 storage system might cause unnecessary controller failover.
SCOS-208	Disks might get a BadRegionsPresent health code during a rebuild, even when they are down, due to the multiple RIPExpired errors.
SCOS-206	Disks might get excessive health codes because of RIPExpired issues codes on devices that are down.

Fixed Issues Related to Replication and Live Volume

The following issues are fixed in Storage Center 7.1.

Table 6. Fixed Replication and Live Volume Issues

Issue	Description
SCOS-14576	Unable to perform Storage Center to PS Series group replication if the Storage Center volume name contains Chinese, German, French, Japanese, or Spanish characters.
SCOS-14065	Thin Import setup is unable to activate the destination volume on a Storage Center when iSCSI is not configured on the storage system.
SCOS-13152	A cross-platform replication snapshot from a PS Series array to a Storage Center might display the wrong volume icon.
SCOS-1928	In ESXi 5.5 or later hosts, the status of a secondary Live Volume remains down after bringing the primary Storage Center back online.
SCOS-706	Converting an existing ESXi datastore volume to Live Volume might cause the volume to disconnect from the ESXi hosts.

Fixed Issues Related to Reporting

The following issues are fixed in Storage Center 7.1.

Table 7. Fixed Reporting Issues

Issue	Description
SCOS-12602	On rare occasions, enabling SNMP causes the SNMP agent to stop unexpectedly and it cannot be restarted.
SCOS-12287	Incorrect SSD endurance tracker alerts might appear if duplicate endurance tracker entries are created.
SCOS-2906	For SCv2000 series storage systems, the Storage Center does not report if the SAS backend is disconnected.
SCOS-2492	In Storage Center 6.6, enabling the AUTH LOGIN option in the SMTP Server settings might cause the email manager to fail.
SCOS-1852	In Storage Center 6.5.10 or later, snapshot messages in system logs might contain an incorrect Position 3072 is past the expected bound error message.
SCOS-1546	The Storage Center admin user does not receive an email when a disk folder is close to being full.
SCOS-1136	When compression is enabled, volume storage usage statistics are not reported correctly.
SCOS-600	In Storage Center 6.5 and 6.6, the SMTP service might not function properly due to ARP reply packet rejection.

Fixed Issues Related to Security

The following issues are fixed in Storage Center 7.1.

Table 8. Fixed Security Issues

Issue	Description
SCOS-10577	Security enhancement regarding the vulnerabilities CVE-2012-4930 and CVE-2012-4929.
SCOS-7936	Security enhancement regarding Apache HTTPD and OpenSSL vulnerabilities.
SCOS-3356	Security enhancement regarding the vulnerability CVE-2015-1283.
SCOS-3254	A controller reset may occur due to a TCP connection LAST_ACK socket state error.

Fixed Issues Related to Storage Management

The following storage management issues are fixed in Storage Center 7.1.

Table 9. Fixed Storage Management Issue in Storage Center 7.1.2

Issue	Description
SCOS-18932	Using Offloaded Data Transfer (ODX) in Hyper-V might result in degraded
	MPIO paths.

Table 10. Fixed Storage Management Issues in Storage Center 7.1.1

Issue	Description
SCOS-17884	When deduplication is enabled, Data Progression may not complete successfully due to memory allocation recovery issues.
SCOS-16576	On rare occasions during a RAID rebalance, a short timing window may occur where inaccurate pagepool information is read from the system resulting in volumes becoming inaccessible for a brief period.
SCOS-15831	A controller reset might occur while modifying or deleting an iSCSI fault domain.
SCOS-15651	Data Progression failures might occur if Data Progression is running on a volume with snapshots that expire at the same time.
SCOS-15239	After updating to Storage Center 7.0, Data Progression times might increase when Compression or Deduplication is enabled.
SCOS-14111	Secondary storage deactivation process is not flushing prefetch pages.
SCOS-13724	A single controller storage system shows servers as partially connected when servers are connected using Fibre Channel.
SCOS-13649	Volumes on separate controllers might show the same deduplication reduction rates when the deduplication reduction rates are different.
SCOS-13159	Deduplication and Compression might take volumes offline when responses to storage type status are incorrect.

Issue	Description
SCOS-10256	Creation of the first volume on a storage system with 7K drives might result in a false PagePool 7K Down alert condition.
SCOS-9946	Data optimization statistics might fail to update after a snapshot coalescence.
SCOS-8853	Data Progression might fail to start after updating a storage system to Storage Center 6.7.
SCOS-8742	Performing a thin import to a destination volume with compression enabled causes all volumes on the storage system with compression enabled to transition to a down state.
SCOS-8543	When the compression feature is enabled for a volume, the volume might become inaccessible.
SCOS-8248	In a Windows 2012 R2 virtual machine running in ESXi 5.5 or Hyper-V on Windows Server 2012, an iSCSI Offloaded Data Transfer (ODX) attempt is causing volume access to hang when the volumes are on different storage systems.
SCOS-7932	Adding a storage system to Dell Storage Manager might fail if the storage system is licensed for SEDs, but it does not have any SED disks.
SCOS-7533	On a storage system with compression enabled, performance degradation might occur during the first few minutes of Data Progression because of table validation.
SCOS-7269	In Storage Center 6.7.5, setting the VLAN Priority to a value above 0 on a fault domain with an iSCSI I/O card that is doing VLAN tagging might prevent iSCSI initiators from logging in.
SCOS-6821	After performing an import from a PS Series storage array, Storage Center continues to attempt to log in to the PS Series storage array, which causes multiple failure logs.
SCOS-3276	Web services under a sustained heavy workload might fail to restart resulting in a loss of access to the Storage Center management interface.
SCOS-2410	On rare occasions, snapshots might fail to expire in Storage Center 6.5.20.
SCOS-1920	Directly connecting to an SCv2000 series storage system with the Dell Storage Client and modifying Storage Center user preferences might result in an error.
SCOS-1200	Command timeouts and errors might occur after installing FIPS WI-SSDs on a storage system running Storage Center 6.6.5.
SCOS-928	Storage systems might report increased memory usage due to improper release of sockets.
SCOS-104	A volume restripe operation with large amounts of compressed data might take an extended amount of time to restripe due to Data Progression errors.
SCOS-100	On rare occasions, Data Progression and subsequent rebalancing might fail due to snapshot full page memory limitations.

Fixed Issues Related to Updating, SupportAssist, and Licensing

The following issues are fixed in Storage Center 7.1.

Table 11. Fixed Updating, SupportAssist, and Licensing Issues in Storage Center 7.1.2

Issue	Description
SCOS-18287	Firmware updates might fail when updating an SCv2000 series storage system or an SC4020 storage system from Storage Center 6.6 to Storage Center 7.1.

Table 12. Fixed Updating, SupportAssist, and Licensing Issues in Storage Center 7.1.1

Issue	Description
SCOS-3438	After updating an SCv2000 series or SC4020 storage system to Storage Center 6.6, performing an update to Storage Center 6.7 might cause performance issues due to improperly handled update file links.
SCOS-3370	Sending diagnostic data using SupportAssist might fail after updating from Storage Center 6.4 or 6.5 to Storage Center 6.6 and later due to previous, pending requests that are unable to complete.
SCOS-2938	Applying the incorrect version of a license file to an SC4020 storage system might cause issues with the Flex Port feature and management of legacy disks.
SCOS-1868	For SC4020 storage systems, an enclosure firmware update might fail due to missing electronically stored information (ESI) paths during installation.
SCOS-694	On rare occasions, when performing a non-service affecting update, a controller may reset due to duplicate and/or overlapping data writes.

Fixed Issues Related to User Management

The following issues are fixed in Storage Center 7.1.

Table 13. Fixed User Management Issues

Issue	Description
SCOS-14309	Storage Center does not restrict directory service communication to manually defined LDAP servers. This issue might cause delays when joining Storage Center to a directory environment or failures when adding directory users and groups to Storage Center for authentication.
SCOS-13835	The password of the Baseboard Management Controller (BMC) resets to the default value after a controller reset.
SCOS-13236	An error might occur in the Dell Storage Manager Client if the user preferences snapshot profile list is invalid.

Open Issues

The following issues are present in Storage Center 7.1.

Open Issues Related to Data Reduction

The following open issues are related to Data Reduction.

Table 14. Open Data Reduction Issues

Issue	Description
SCOS-19002	Enabling deduplication on a storage system while one controller is in a failed state might result in volumes that appear to be deduplicated, when in fact they are not deduplicated. Workaround: Contact Dell Technical Support.
SCOS-13237	The Storage Type Data Reduction statistics might be incorrect if the amount of data eligible for Data Reduction contains fewer than 256 pages. Workaround: None

Open Issues Related to Hardware

The following open issues are related to hardware.

Table 15. Open Hardware Issues

Issue	Description
SCOS-18759	The QLe246x Fibre Channel I/O Card takes longer to rebalance in Storage
	Center 7.1 than it did in previous versions of Storage Center.
	Workaround : The QLe246x I/O card is not supported in Storage Center 7.1 and must be replaced with a supported Fibre Channel I/O card.
SCOS-18490	When connected directly to the Storage Center using the Dell Storage
	Manager Client, an error occurs in the hardware change wizard while
	performing a hardware migration from an SC040 running Storage Center 6.7 to an SC8000 running Storage Center 7.1.
	Workaround : Connect to the Storage Manager Data Collector using the Dell Storage Manager Client and then run the hardware change wizard on the Storage Center.
SCOS-18174	On SC7020 storage systems, the status of a new Liebert UPS is not changing
	from DC to AC in the Dell Storage Manager Client when power is restored to the UPS.
	Workaround: None
SCOS-10427	On rare occasions, an SCv2000 series or SC4020 storage system may not initialize following a reset or power cycle.
	Workaround : Reboot the storage system by performing a power cycle on the controllers. After the controllers are power cycled, the storage system boots up successfully.
SCOS-6516	On rare occasions, the internal boot device on an SC9000 controller may become unusable following an unexpected power event and the controller will not boot.

Issue	Description
	Workaround: Contact Dell Technical Support.

Open Issues Related to Replications and Live Volumes

The following open issues are related to replications and Live Volumes.

Table 16. Open Replication and Live Volume Issues

Issue	Description
SCOS-18102	The status of a cross-platform replication partner changes to down when the number of snapshots exceed 1025.
	Workaround : The maximum number of supported snapshots for a cross-platform replication is 512. To resolve this issue, manually remove the snapshots until there are less than 512 snapshots and change the expiration dates of snapshots for the replication volume to a manageable expiration time.
SCOS-17981	Server mappings may not be completely removed when a server is removed from an OS cluster using Dell Storage Manager prior to the server being removed from the OS cluster.
	Workaround : Remove the server from the cluster through the OS first. After the server is rebooted, remove the server object using Dell Storage Manager.
SCOS-12067	When importing a volume, Storage Manager does not allow you to select 0 as the LUN number. Workaround: None

Open Issues Related to Storage Management

The following open issues are related to Storage Management.

Table 17. Open Storage Management Issues

Issue	Description
SCOS-14951	After deleting volumes and snapshots, Storage Center does not immediately report the deleted volume space as free space for a disk folder. Workaround: Contact Dell Technical Support.
SCOS-8627	AIX servers cannot boot from SAN using Dell Storage Software Suite for AIX version 2.2.0.17.
	Workaround : Use the latest version of Storage Center and the Dell Storage Software Suite for AIX listed in the <i>Dell Storage Compatibility Matrix</i> .

Open Issues Related to Updating, SupportAssist, and Licensing

The following open issues are related to updating, SupportAssist, and licensing.

Table 18. Open Updating, SupportAssist, and Licensing Issues

Issue	Description
SCOS-18488	The Storage Center System Manager user interface is not disabled after updating a dual-controller storage system from Storage Center 6.6.5 to Storage Center 7.1.1.
	Workaround: Reboot the storage system.

Open Issues Related to User Management

The following open issues are related to Storage Center user management.

Table 19. Open User Management Issues

Issue	Description
SCOS-11192	Storage Center cannot authenticate directory service users that are configured to use an alternate DNS suffix.
	Workaround: None

Open Issues Related to Vendors

The following open issues are related to vendors.

Table 20. Open Vendor Issues

Issue	Description
SCOS-18203	In certain degraded conditions, data miscompares might occur when running software FCoE on an Intel X520 adapter in an ESXi 5.5 or 6.0 host.
	Workaround : Issue has been escalated with VMware. See the <i>Dell Storage Compatibility Matrix</i> for updates.
SCOS-18123	Fibre Channel volumes that are mapped to a Hyper-V virtual machine using NPIV are not discovered by the virtual machine when the server has a QLogic HBA with out-of-date drivers.
	Workaround : Update the HBA to the latest version of the QLogic driver listed in the <i>Dell Storage Compatibility Matrix</i> .
SCOS-17996	An ESXi 5.5 or 6.0 host with an Emulex FC/FCoE HBA running driver version 11.0.x.x might crash during a controller failover.
	Workaround : Update the Emulex FC/FCoE HBA to driver version 11.1.145.18, which is available on the VMware website.
SCOS-16820	Software FCoE timeouts might occur when using QLogic CNAs in NIC mode. Workaround : See the <i>Dell Storage Compatibility Matrix</i> for the list of supported firmware and drivers.

Issue	Description
SCOS-10166	Emulex FC and FCoE driver version 10.7.170.0 might cause an ESXi 5.5 or 6.0 host to fail during controller failovers.
	Workaround: Use the latest recommended driver version for the Emulex adapters. See the <i>Dell Storage Compatibility Matrix</i> .
SCOS-10155	Data Center Bridging bandwidth utilization of traffic classes might cause I/O to stop on iSCSI initiators when using an Intel X520 Dual Port 10 Gb server adapter.
	Workaround: None.
CQ00358236	ESXi 5.x hosts with QxE82xx iSCSI adapters using QLA4xxx driver version 634.5.18 (ESXi 5.1) or 6.34.55.20 (ESXi 5.5) might fail to log in to the Storage Center after a controller reset or failover.
	Workaround: Use the latest recommended driver version for the QLogic adapters. See the <i>Dell Storage Compatibility Matrix</i> .
CQ00252780	On a storage system with iSCSI front-end ports, if a controller or port is in a failover process when a Windows boot from SAN is requested, the boot might fail.
	Workaround: Subsequent boot from SAN requests succeed when the controller or port is up.

Storage Center Update Information

The following information must be considered before updating to Storage Center 7.1.

A storage system must be running Storage Center 6.6.4 or later to perform a SupportAssist update to Storage Center 7.1. For more information, see the *Dell Storage Center Software Update Guide*.



NOTE: When performing an update of both Storage Center and Dell Storage Manager, update Dell Storage Manager before updating Storage Center.

Support Resources

The following section provides resources for finding more information on using a Storage Center storage system.

Related Documentation

The following documents are available for a storage system running Storage Center 7.1.

- Dell Storage Center Software Update Guide

 Describes how to update Storage Center software from an earlier version to the current version.
- Dell Storage Center Update Utility Administrator's Guide
 Describes how to use the Storage Center Update Utility to install Storage Center software updates.
 Updating Storage Center software using the Storage Center Update Utility is intended for use only by sites that cannot update Storage Center using standard methods.
- Dell Storage Manager Installation Guide Provides installation and setup instructions.

- Dell Storage Manager Administrator's Guide
 Provides instructions for using the Data Collector Manager and the Dell Storage Manager Client.
- Dell Storage Manager Online Help
 Provides context-sensitive help for the Dell Storage Manager Client, Data Collector Manager, and Storage Manager Server Agent.
- Dell Storage Manager Release Notes
 Provides information about Dell Storage Manager releases, including new features, enhancements, fixed issues, and open issues.
- Dell Storage REST API Release Notes
 Provides information about the Dell Storage REST API, which allows you to manage the Storage Manager Data Collector and Storage Centers.

Finding Documentation

The following locations contain documentation for a storage system running Storage Center 7.1.

- Dell Support
 Provides documentation for Dell storage products. Go to www.dell.com/support.
- Dell TechCenter
 Provides technical white papers, best practice guides, and frequently asked questions about Dell storage products. Go to http://en.community.dell.com/techcenter/storage/.

Contacting Dell

Dell provides several online and telephone-based support and service options. Availability varies by country and product, and some services might not be available in your area.

To contact Dell for sales, technical support, or customer service issues, go to www.dell.com/support.

- For customized support, type your system service tag on the support page and click **Submit**.
- For general support, browse the product list on the support page and select your product.

^{© 2016} Dell Inc. All rights reserved. This product is protected by U.S. and international copyright and intellectual property laws. Dell and the Dell logo are trademarks of Dell Inc. in the United States and/or other jurisdictions. All other marks and names mentioned herein may be trademarks of their respective companies.